

PREVENT FOREIGN OBJECT DAMAGE PREVENT DROPPED OBJECTS

REPORT TO:

100 ARW FOD/DOP
PROGRAM MONITOR

Primary

TSgt Drake Morvant

X-6885

Bldg. 809 Rm. 2.33

100 ARW FOD/DOP
PROGRAM MONITOR

Alternate

TSgt Tristan Williams

X-6889

Bldg. 809 Rm. 2.33

WAYS YOU CAN PREVENT FOD & DROPPED OBJECTS:

1. BY EXERCISING "CAUTION" NEAR OPERATING JET ENGINES.
2. BY USING GOOD HOUSEKEEPING I.E. PICKING UP TOOLS AND CLEANING AS YOU GO.
3. BY INSPECTING VEHICLES AND TIRES PRIOR TO USE ON THE FLIGHTLINE.
4. BY ENSURING ALL FASTNERS ARE SECURE.

5. BY REQUESTING VACUUM OR MECHANICAL SWEEPERS FOR NOTICEABLE DEBRIS ON AIRFIELD THROUGH WING MAINTENANCE OPERATIONS CENTER (MOC) OR BASE OPERATIONS.

6. BY ENSURING ALL DOORS AND PANELS ARE SECURE PRIOR TO AIRCRAFT FLIGHT.